

PATINA RESTORATION KIT APPLICATION INSTRUCTIONS

Read instructions in full before proceeding. If you have any questions please contact info@premiercopperproducts.com or call 602-476-7332.



1. PREPARATION

Before applying the gel, ensure that the copper surface is clean and free of any dust, dirt, or debris. You may need to wash the surface with mild soap and water and a soft sponge or cloth and allow it to dry completely. For best results, clean with denatured alcohol to remove any contaminants.



2. APPLICATION

Wear gloves and protective eyewear before handling the patina gel. Warm the copper surface with a hair dryer or heat gun, only until warm, not hot. Perform a small test patch in an inconspicuous area before treating the entire surface to ensure compatibility and desired results.

Apply the copper patina gel in a very thin, even layer to the copper surface using provided sponge. Ensure complete coverage of the areas you are treating.



3. CURING TIME

Apply additional heat to instigate chemical reaction. Apply additional patina gel with sponge as needed.



4. MONITORING

During the curing time, you will be able to see the progress of the patina development. You may notice changes in color or texture as the gel works on the surface.



5. RINSING

Once satisfied with the color of patina restoration, rinse the copper surface thoroughly with cool clean water to stop the darkening of the patina gel.



6. DRYING

Once rinsed, remove the gel and any residue. Use a clean sponge or soft cloth for complete removal. Dry the copper surface thoroughly with a new clean, dry cloth to prevent water spots or streaks from forming.



7. OPTIONAL STEPS

Using the provided wet sandpaper, dampen the sandpaper and gently rub in a circular motion to brighten high spots on hammered copper finish.

You may choose to apply additional coats of gel or apply our Spray Wax Protectant (W900-WAX) to enhance the patina or provide additional protection to the surface.



8. CLEANUP

Dispose of any used materials properly according to local regulations. Clean brushes or tools with soap and water.



9. MAINTENANCE

Regularly apply our protectant spray wax (W900-WAX) to maintain proper luster of the copper surface. Depending on environmental factors, you may need to repeat the patina restoration process periodically to maintain the desired appearance.



CARE INSTRUCTIONS

Scan here to view our copper care instructions. Please note, finish is not covered under our warranty.



INSTRUCTIONAL VIDEO

NOT FOR HUMAN CONSUMPTION Always follow the specific instructions provided by the manufacturer of the copper patina gel you are using, as formulations and application methods may vary.

INFO@PREMIERCOPPERPRODUCTS.COM | PREMIERCOPPERPRODUCTS.COM
425 E. PINNACLE PEAK RD. STE 170, PHOENIX, AZ 85024 | (602) 476-7332



PREMIER
COPPER PRODUCTS